

## Features:


1. Fiber mode: SM, MM( OM2/OM3/OM4/OM5
2. Connector: FC,SC,ST,LC,MU,MTRJ,E-2000
3. Jacket Colors: orange,yellow, purple,aqua,green
4. Ferrule: PC,UPC,APC
5. Insertion Loss:  $\leq 0.2\text{dB}$
6. Quality standards : CE , ISO9001

## Strict producing procedures:

**Cable cutting**



**Cable clear up**



**Pre-handling**



**Jacket stripping**



**Cable identify**



**Cladding stripping**



**Glue injection**




**Fiber inserting**



**Fiber solidifying**



Fasten by jig



Polishing



Ultrasonic clearing



Microscope inspection



Crimp junction



Kits assembly



FQC



Packaging



I.L & R.L inspection

